



Speed-Vap® III Evaporation System and Solvent Trap™

To keep the evaporation and solvent trap in good working conditions, the following items should be checked and replaced per the recommended frequency below.

Ref	Part #	Quantity Required	Description	Frequency
1	02-0302-02	1	Lid Gasket	Inspect every 12 months, replace if worn or damaged
2	02-0302-01	1	Bottom Gasket	Inspect every 12 months, replace if worn or damaged
3	50-0572	1	Dry Trap - (Goes in Air Supply Line as a Filter)	Inspect every 6 months, replace if worn or damaged
4	50-0487	1	Air Supply Line for the Speed-Vap III	Inspect every 12 months, replace if worn or damaged
5	50-0488	1	Vacuum line for the Speed-Vap III and Solvent Trap	Inspect every 12 months, replace if worn or damaged
6	50-0489	1	Exhaust Line for the Speed-Vap III	Inspect every 12 months, replace if worn or damaged
7	27-0871	1	500-mL Erlenmeyer Flask for the Solvent Trap	Inspect every 12 months, replace if worn or damaged
8	20-0573	1	Rubber Stopper for the Erlenmeyer Flask in the Solvent Trap	Inspect every 12 months, replace if worn or damaged
9	99-0326	1	Cleanout wire for holes on the lid of the Speed Vap	Inspect every 12 months, replace if worn or damaged